

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer/Assistant Executive Engineer)

- Name of school : **The Oxford School, Pantheerankavu**
1. Name of Officer : **Thushara .PR**
2. Location : **Pantheerankavu**
3. Period for which the certificate is issued : **2022-23**
4. Types of building : } **RCC, Basement Floor - 348.39 m² - Office**
5. Nature of defect if any:- **Ground Floor - 934.48 m² - KG Section- 7 nos**
- a) Foundation and basement : **Nil** **First Floor -1756.49m² -Classes Primary - 9 nos**
- b) Superstructure : **Nil** **Second Floor- 2062.86m²- Classes&lab - 14 nos**
- c) Doors and windows : **Nil** **Third Floor - 2062.85m² ,Classes - 10 nos**
- d) Wood work wrought up : **Nil** **Total Plinth area - 7165.06 m²**
- e) Roof : **Nil**
- f) Flooring : **Nil**
- g) miscellaneous(Cracks if any) : **No visible cracks found**
6. Any major defects noticed which will render the building unsafe in any manner: **Nil**
7. Whether maintenance work have been done properly : **Yes**
8. Whether the structure is sound or not for conducting classes : **Sound for conducting classes under normal wind and Weather condition**


Note: 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2. Any additional observation deemed necessary for the necessary for the certificate, may be furnished separately with the Certificate

Certified that the school was inspected by me on 25/5/22 and found to be **Fit** to conduct classes for the period for the stated above

Place: Mathan
Date: 25/5/22



Signature 
Assistant Engineer
LSGD Section, Olavanna
Olavanna Grama Panchayat
ASSISTANT ENGINEER
L. S. G. D. SECTION
OLAVANNA GRAMA PANCHAYAT