

**TO BE FILLED BY THE INSPECTING OFFICER**  
(Assistant Engineer/Assistant Executive Engineer)

Name of School		The Oxford School, Pantheerankavu
1	Name of Officer	Ashwathy B
2	Location	Pantheerankavu
3	Period for which the certificate is issued	2023-24
4	Types of building	RCC, Basement Floor - 348.39 m <sup>2</sup> - Office Ground Floor - 934.48 m <sup>2</sup> - KG Section - 7 nos First Floor - 1756.49m <sup>2</sup> -Classes Primary - 9 nos Second Floor- 2062.86m <sup>2</sup> - Classes&lab - 14 nos Third Floor - 2062.85m <sup>2</sup> ,Classes - 10 nos <b>Total Plinth area - 7165.06 m<sup>2</sup></b>
5	Nature of defect if any	
	a Foundation and basement	Nil
	b Superstructure	Nil
	c Doors and windows	Nil
	d Wood work wrought up	Nil
	e Roof	Nil
	f flooring	Nil
	g miscellaneous (cracks if any)	No visible cracks found
6	Any major defects noticed which will render the building unsafe in any manner	Nil
7	Whether maintenance work have been done properly	Yes
8	Whether the structure is sound or not for conducting classes	Sound for conducting classes under normal wind and Weather condition
Note	1	The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
	2	Any additional observation deemed necessary for the necessary for the certificate, may be furnished separately with the Certificate
Certified that the school was inspected by me on <b>23/05/2023</b> and found to be <b>Fit</b> to conduct classes for the period for the stated above		
Place: Olavanna		
Date : 23/05/2023		

Signature  
Assistant Engineer



ASSISTANT ENGINEER  
LID & EW SECTION  
OLAVANNA